

Robot picture



Robot name : Persia

Number of degree of freedom
20

Computing unit
Gumstix or CMU3 & microcontroller

Walking speed
18 cm/s

Camera
Webcam or CMU3

Sensors
Gyro and servo motor feedbacks

Other specs

AX 12+ servomotors